

FIGURE 27
MASS REMOVAL RATES: IRON
ST. LOUIS TUNNEL DISCHARGE CONSTRUCTED WETLAND
PILOT SCALE TEST COMPLETION REPORT
 Rico-Argentine Mine Site
 Dolores County, Colorado




FIGURE 28
MASS REMOVAL RATES: MANGANESE
ST. LOUIS TUNNEL DISCHARGE CONSTRUCTED WETLAND
PILOT SCALE TEST COMPLETION REPORT
 Rico-Argentine Mine Site
 Dolores County, Colorado




FIGURE 29
MASS REMOVAL RATES: CADMIUM
ST. LOUIS TUNNEL DISCHARGE CONSTRUCTED WETLAND
PILOT SCALE TEST COMPLETION REPORT
 Rico-Argentine Mine Site
 Dolores County, Colorado




FIGURE 30
MASS REMOVAL RATES: ZINC
ST. LOUIS TUNNEL DISCHARGE CONSTRUCTED WETLAND
PILOT SCALE TEST COMPLETION REPORT
 Rico-Argentine Mine Site
 Dolores County, Colorado

